

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Budget Bureau No. 43-2382.4  
Approval expires 12-31-63.

Indian Agency Navajo  
Allottee Contract #96  
Lease No. Navajo

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY  
FARMINGTON, NEW MEXICO

August 21

1961


Well No. 9 is located 870 ft. from S line and 1750 ft. from E line of sec. 8  
SE/4 Sec. 2 24N 30 107W  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Corral Pictured Cliffs San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the ground above sea level is 7024 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud 9 A.M. 8-9-61. Dred 9-7/8" hole to 100'.  
Spud 11 jts (110') of 7-5/8", 26# casing at 100' with 125 cas + 25 Collg.  
Fing down at 9:15 P.M. 8-9-61. Circulated cement to surface.  
Tested casing with 650 psi for 30 min. with no loss in pressure.  
Drilling ahead.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Southern Mobil Oil Company, Inc.

Address P. O. Box 3372  
Durango, Colorado

By P. M. Barry  
F. M. Barry  
Title Dist. Producing Eng.