. Form 2, 101 (May, 1990)	DEPARTI	UNITED STATES MENT OF THE INTE SCOLOGICAL SURVEY	-	on re-		od. 195 No. 40 H1 424 , 1816 AFETAS, NO. 7	
(Do not as	of this form for propos	ICES AND REPORTS	us back to a different reservoir	G in this		; on them saving	
1. OIL X VIII OTHER 2. NAME OF OPERATOR					T. PART AGGINEST COME. LUST BIOTH Unit 8. FARM OR LEADE NAME.		
Skelly 3. ADDRESS OF OF	Oil Company						
1860 Li	ncoln Street,	Denver, Colorado	80203	9. WELL N	o. 55		
4. LOCATION OF WILL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990 FNL & 1650 FWL Section 31-25N-10W					Bisti Lower Gallup		
990	0. FNL & 1650	FWL Section 31-2	5N-10W	nti Ra	TET OR ABEA		
14. PERMIT NO.		15. ELEVATIONS (Show whether	er DF, RT, QR, etc.)		7 OR PARTRO	-25N-10W 13. MTATE New Mexico	
16.	Check Ap	propriate Box To Indicat	e Nature of Notice, Report,	, or Other Data		Commission of the Commission o	
	NOTICE OF INTEN	TION TO:	,	UBSEQUENT REPORT	១៩:		
TEST WATER S FRACTURE TRE SHOOT OR ACH REPAIR WELL (Other)	AT DIZE	ABANDON* THANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZIN (Other) (Note: Report Completion or R		ALTERING CA	17.	
All de	epths shown ar vell has reach	e from Ground Leve	el. mit and is no longe	er profitabl	OIL CON	r. 3	
First	Plug - (5074	'- 5174') 100' p	tug across the Gallu	p Zone Perf	s. 5104	-5150'	
Second	Plug- 50' in	side of the 5-1/2	casing and 50' abo	ve where ca	sing is	shot in two	
Third			lug extending downwa Pictured Cliffs Sa		ve the	Fruitland	
Fourt	Plug- (670 botto	'- 770') 100' pi m of the Ojo Alamo	lug extending from 5 Sand	0' above to	50' be	low the	
10 sac	ks of cement	in top of surface	casing with dry hol	e marker		<i>}</i> 1	
				-			
				•			
18. I hereby certif	that the foregoing is	true and correct	Lead Clerk	DATI	July	16, 1971	
(This space for	r Federal or State offi	ce use)			N. T		
APPROVED B'	YOF APPROVAL, IF A	NY:		DATI	ē		