


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico
Lease No. 87-079395
Unit M



RECEIVED

JAN 28 1959

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


Well No. 45 is located 660 ft. from N line and 660 ft. from E line of sec. 26
81-07 (1/4 Sec. and Sec. No.) 25N (Twp.) 14W (Range) N.M.P.M. (Meridian)
Dist. Lower Gallup (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5745 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

12 1/2" hole was drilled to 270'. 252.17' of 9 5/8" 32.30 lb. H-40 casing was set at 263.17' and cemented with 125 sac cement. The plug was down at 10:00 A.M. January 18, 1959. The cement was allowed to set 24 hrs. and the job was tested with 500 lbs. for thirty minutes with no pressure drop.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Frank O. Elliott & Ore R. Hall, Jr.

Address Box 703

Roswell, New Mexico

By [Signature]

Title

Agent