

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Navajo Allocated

Allotter Window Rock

Lease No. 14-20-603-1378

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<div style="text-align: center;"> </div>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 18, 19 57

Hah-Gee-Don-Pah Estate

Well No. 1 is located 990 ft. from S line and 660 ft. from E line of sec. 30

25 of Sec. 10 25N 10W ENPM
(4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

<u>Dist</u>	<u>San Juan County</u>	<u>New Mexico</u>
(Field)	(County or Subdivision)	(State or Territory)

The elevation of the ~~dam~~^{dam} above sea level is 6699 ft. **Ground**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 7 7/8 Hole to 5275'. Set 5 1/2 14" J55 Casing at 5274' and cemented with 150 sacks of 90-50 Portland & 2% Gel. Top of the cement at 4400' by Temperature Survey. Casing was tested to 18000' with no pressure drop. Centralizers & Scratches were used in setting casing.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Energy Midcontinent Oil Co.

Address 411 West Main

Parvington, New Mexico

Bv.

Title ~~Group Person~~