

Carson - Shell

(FIELD)

DRILLING REPORT

FOR PERIOD ENDING

October 15, 1956

WELL NO. 27

27

(SECTION OR LEASE)

T 25 N, R 11 W.

(TOWNSHIP OR RANCHO)

San Juan County, New Mexico

(COUNTY)

DAY 1956	DEPTHS		REMARKS
	FROM	TO	
			Location: 1980' N and 660' W from the SE Corner, Section 27, T. 25 N., R. 11 W., N.M.P.M., San Juan County, New Mexico. Elevations: DF 6729.65' MAT 6722.20' KB 6731.65'
10-3	0	230	Drilled 230'. Spudded 9:00 P.M., 10-3-56. Ran and cemented 8-5/8", 32#, J-55 casing at 219' with 130 sacks treated construction cement. Finished 3:30 A.M., 10-4-56.
10-4	230	1355	Drilled 1125'. Flanged up. Pressure tested BOP and casing with 700 psi for 15 minutes, OK.
10-5 to 10-14	1355	5308 TD	Drilled 3953'. Ran Electrical Survey and Microlog.
10-15			Ran in to condition mud, mud would not circulate. Pulled to 3060' off bottom before circulation could be obtained. Circulated and worked back to bottom. Ran and cemented 4-1/2", 10.8# drill tubing as casing at 5296' with 200 sacks construction cement. Finished 8:45 P.M. Flanged up. Checked BOP daily Mud Summary -- 10-8-56 to 10-15-56 Wt. 10.1 - 10.4#/gal Vis. 41 - 48 sec WL 8.2 cc FC 2/32 in.
CONDITION AT BEGINNING OF PERIOD			
HOLE			CASING SIZE
SIZE	FROM	TO	DEPTH SET
DRILL PIPE SIZES			



G. Gregory

SIGNED