

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
L. M. Phillips No. 1
SF 078063
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Water Injector	7. UNIT AGREEMENT NAME Carson Unit
2. NAME OF OPERATOR Shell Oil Company	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR 1700 Broadway, Denver, Colorado 80290	9. WELL NO. 11-30
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 660' FWL Section 30	10. FIELD AND POOL, OR WILDCAT Bisti
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6471.1' KB
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 30-T25N-R11W
	12. COUNTY OR PARISH San Juan
	13. STATE N. Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data


NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) <input type="checkbox"/>			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

See attachment

WILL SEND FINAL SUNDRY WHEN LOCATION
CLEANED AND READY FOR INSPECTION



18. I hereby certify that the foregoing is true and correct

SIGNED L. P. Plaudy TITLE Div. Ops. Engr. DATE JUL 29 1977

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

cc: New Mexico O&GCC w/attachment

PLUG AND ABANDON WELL

SHELL OIL COMPANY

FROM: 6/17-20/77

LEASE	CARSON UNIT	WELL NO.	BISTI 11-30
DIVISION	WESTERN	ELEV	6471.1 KB
COUNTY	SAN JUAN	STATE	NEW MEXICO

NEW MEXICO

BISTI FIELD

Carson Unit 11-30
(P&A)

"FR" TD 4960. PB 4911. AFE 528916 provides funds to Plug and Abandon. Install cast iron BP. Rig up Bedford Inc, unseat 4-1/2 pkr. Pulled & LD 156 jts tbg. Started back in hole with tbg. JUN 17 1977

Carson Unit 11-30
(P&A)

TD 4960. PB 4911. 6/17 Ran tbg to PBTD. Loaded hole w/mud. Spt'd 20 sx cmt mixed w/1# flocele/sx over & above perfs. Pulled & LD tbg. RU hyd jacks. Shot off csg @ 1246. Spt'd 50 sx cmt plug across csg stub. Pulled csg to base of Ojo Alamo & SD. 6/18 Spt'd 35 sx cmt across base of Ojo Alamo. Pulled csg to base of 8-5/8 csg & spt'd 25 sx cmt. Fin'd pull'g csg. Put in 10 sx cmt plug @ sfc. Installed abandonment marker. RD Bedford 6/20/77.
FINAL REPORT

JUN 20 1977