

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency -----

A. F. 100

Allottee -----

Lease No. -----

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	TRAC X
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 1 is located 330 ft. from [N] line and 1650 ft. from [E] line of sec. 25

~~NY 4~~ ~~Sec. 25~~ ~~(Page)~~ ~~(Edition)~~
 (Sec. and Sec. No.)

~~District~~ _____ ~~No.~~ 70811
(Filed) (County or Subdivision)


The elevation of the derrick floor above sea level is 66.0 ft.

DETAILS OF WORK

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

pulling tubing and fractured down 5 1/2" casing through perforations 5100-5107 and 5114-5126/ Schlumberger measurements, with 20,000 gallons lease oil and 20,000# sand in two stages using 55 rubber balls. Test 4-18-58 flowed 114 BBL and 32.3 M in 24 hrs., 21/64" choke, TP 160#, CP 0 #.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Monroe Mid-Continent Oil Company

Address Box 128

Hobbs, New Mexico

By ~~U.S. District Court~~

Title 312 Deer

