

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
E. W. Mudge No. 3
SF 078064
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME Carson Unit
2. NAME OF OPERATOR Shell Oil Company	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR 1700 Broadway, Denver, Colorado 80290	9. WELL NO. 44-24
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL & 660' FEL Section 24	10. FIELD AND POOL, OR WILDCAT Bisti
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6464 KB
	12. COUNTY OR PARISH San Juan
	13. STATE N. Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) <input type="checkbox"/>		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

See attachment

WILL SEND FINAL SUNDRY WHEN LOCATION
CLEANED AND READY FOR INSPECTION



18. I hereby certify that the foregoing is true and correct

SIGNED R. P. Plaudy TITLE Div. Oper. Engr. DATE JUL 29 1977

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

cc: New Mexico O&GCC w/attachment

PLUG AND ABANDON WELL

SHELL OIL COMPANY

FROM: 6/15-17/77

LEASE

CARSON UNIT

DIVISION

WESTERN

COUNTY

SAN JUAN

WELL NO.

ELEV

STATE

BISTI

44-24

6464 KB

NEW MEXICO

NEW MEXICOBISTI FIELD

Carson Unit 44-24

(P&A)

"FR" TD 5025. AFE #528926 provides funds to plug and abandon well. 6/11 RU Bedford. Found tbg prt'd @ 1860'. Pulled tbg to look @ btm jt. Ran tbg back in to top of fish. Tried to screw into the tbg; able to do so, but tbg would pull apart. Pulled tbg again. Ran in overshot on tbg; got onto fish. Pulled all tbg string out of hole. Found collar on the fish was split. Ran tbg workstring back to tbg fish originally left in hole @ 49:29. Loaded hole w/mud. Circ'd oil out of hole. 6/14 Spt'd 20 sx Class G cmt mixed w/1#/sx flocele over & above perms. Pulled & LD tbg. RU hyd jacks.

JUN 15 1977

Carson Unit 44-24

(P&A)

TD 5025. Shot off csg @ 1216 & spt'd 50 sx cmt plug across stub. Pulled csg to base of Ojo Alamo & spt'd 35 sx cmt plug. Pulled csg to base of 8-5/8" 165' & spt'd 25 sx cmt plug. Fin'd pull'g csg. RD Bedford 6/15/77. Prep to install sfc plug & abandonment marker.

JUN 16 1977

Carson Unit 44-24

(P&A)

TD 5025. 10 sx cmt plug at surface. Installed abandonment marker.

FINAL REPORT

JUN 17 1977