


Section 24

(SUBMIT IN TRIPLICATE)

Indian Agency Window Rock Ariz.

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Contract 14-20-603-1438

Allottee W-2934

Lease No. Deft-30-3a

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

OCT 28 1957

OCTOBER 24, 1957


Well No. 1 is located 660 ft. from EN line and 1973 ft. from EW line of sec. 24  
SW, SE, Section 24 25-N 11-W N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Histi (Lower Gallup) San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6524 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

after setting 5175' of 5 1/2" Casing on bottom at 5175' with 150 sx cement.  
Did not Circulate. Tested 5 1/2" Casing with 1000# for 30 minutes before and  
after drilling plug. Tested OK. No Break.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company MIDLAND PETROLEUM COMPANY  
Address P.O. BOX 633  
MIDLAND, TEXAS  
By Harve H. Myfield  
Title ASST. Division Superintendent

