UNITED STATES SUBMIT IN TRIPLICATE*  (May 1963)  **DEPARTMENT OF THE INTERIOR**  Other Instructions on re- verse side)	Form approved. Budget Bureau No. 42-R1424. LEASE DESIGNATION AND SERIAL NO.
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)	Mims No. 1 SF 078067 6. IF INDIAN, AULOTTEE OR TRIBE NAME
i.	7. UNIT AGREEMENT NAME
OIL GAS WELL OTHER Water Injector  2. NAME OF OPERATOR	Carson Unit 8. FARM OR LEASE NAME
Shell Oil Company 3. ADDRESS OF OPERATOR	9. WELL NO.
1700 Broadway, Denver, Colorado 80202	43-23
4. Location of Well (Report location clearly and in accordance with any State requirements.  See also space 17 below.)	10. FIELD AND POOL, OR WILDCAT
At surface	Bisti 11. sec., t., b., m., or blk. and
3300' FNL & 660' FEL Section 23	Section 23-T25N-R12W
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
6418' KB	San Juan New Mexico
Check Appropriate Box To Indicate Nature of Notice, Report, or C	Other Data
NOTICE OF INTENTION TO:	JENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	RE. AIRING WELL
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE  ABANDON*  SECOTING OR ACIDIZING  CHANGE PLANS  (Other)	ABANDONMENT*
(Note: Report results	of multiple completion on Well letion Report and Log form.)
See attachment	
	NOV 5 18/5 OIL CON. COM. DIST
18. I hereby certify that the foregoing is true and correct  SIGNED  TITLE Div. Opers. Ergr.  (This space for Federal or State office use)  APPROVED BY	DATE

WELL PLUGGED AND ABANDONED		
SHELL OIL COMPANY	LEASE CARGON INTE	BISTI
, =	LARSIN UNIT	WELL NO. 43-23 WI
FROM: 0.400	DIVISION LIESTERM	
FROM: 9/29 - 10/7/75	COUNTY SAN JUAN	0418 KB
	DAN JUAN	STATENEW_MEXICO

NEW MEXICO
BISTI FIELD
Carson Unit 43-23 WI

"FR" TD 4945. Prep to P&A. MI&RU Farmington Well Service to pull pkr. Attempted to bleed off wellhead. Well blw'g gas & oil. SI for night. 9/27 Well SI; 200# tbg press. Blew well to pit & brought off wellhead press. Attempted to remove slip type wellhead donut w/tension pkr in hole & couldn't. SI well. SEP 29 1975

Carson Unit 43-23 WI

TD 4945. Pulled tbg up & set slips. Filled annulus w/wtr. Released pkr. Pulled 152 jts 2-3/8 tbg. Removed pkr & ran back in hole w/2-3/8 tbg. Tagged btm @ 4870. Pulled 2 jts & SI well.

(RDUFA)

SEP 30 1975

Carson Unit 43-23 WT

TD 4945. (RRD 9/30/75) MI&RU Sigoro. Circ'd hole clean. Mixed & circ'd 15 sx mud. Mixed & spt'd 20 sx cmt on btm. Est top of cmt 4650. Pulled & LD 2-3/£ tbg. MI&RU csg jacks & SD for night. 10/4 PU on csg to remove slips & csg parted. Attempted to screw csg back in; could not. RU & pulled 256' csg. Removed bad jt & ran back in hole w/4-1/2 csg & screwed into csg stub. Stretched & worked pipe. Had approx 1150' free. SD for weekend.

Carson Unit 43-23 WT

TD 4945. Worked csg; unable to work loose below 1135'. Ran in to shoot off csg; could not shoot below 845'. Shot csg off @ 820'. Pulled up 10' & spt'd 50 sx cmt plug from 820-600'. Pulled up to 330' & spt'd 55 sx plug from 330-70'. Pulled remainder 4-1/2" csg & spt'd 10 sx plug in csg @ surface & installed permanent abandonment marker. Recovered 820' of 4-1/2" csg. Well P&A.

OCT 0.7 1975