

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe, N.Mex.  
Lease No. SP 07806 4  
Unit Carson Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<b>RECEIVED</b> <b>APR 30 1958</b> <b>U.S. GEOLOGICAL SURVEY</b> <b>FARMINGTON, NEW MEXICO</b>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHUT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 23-24 is located 3300 ft. from N line and 1979 ft. from E line of sec. 24  
SW 24 (1/4 Sec. and Sec. No.) 25N (Twp.) 12W (Range) NMPM (Meridian)  
S 1st (Field) San Juan (County or Subdivision) New Mexico (State or Territory)


The elevation 6450 ft. (approx. Ground)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 4-22-58

4-22, 23-58 Ran and cemented 3-5/8" 24lb, 1-55 casing at 103' with 100 sacks treated cement. Good returns to surface. Flanged up and waited on cement. Tested SOP and casing with 700 psi. 15 min., ok.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company  
Address 101 S. Behrend  
Farmington, New Mexico  
By H. E. Methuen  
H. E. Methuen  
Title Exploitation Engineer