



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

Santa Fe, N. M.

Land Office SF 078064
Lease No. Carson
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 8, 1957

Carson Unit
Well No. 33-24 is located 1980 ft. from N line and 1980 ft. from E line of sec. 24
N 24 25 N 12 N N 24
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Hidalgo San Juan Ne. Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6465 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

(Spudded 12-29-56)

12-29-56 Ran and cemented 207' of 5 1/8", 23 lb./ft. casing at 220' with 150 sacks treated to construction cement. Good cement returns to surface. Slugged up. Pressure 12-30-56 tested blowout equipment and casing with 700 psi for 15 minutes, O.K.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company
Address 33 Richards Street
Salt Lake City, Utah
By B. W. Shepard
B. W. Shepard
Title Exploitation Engineer

