X 24

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

_	Bureau No. 42-R358.4.		
and Offic	Santa Fe, N.M.		
SF-078064			
Init	Carson		

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	s	UBSEQUENT REPORT OF WATER SHO	JT-OFF
NOTICE OF INTENTION TO CHANGE PLANS.	SI	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SH	HUT-OFFSI	UBSEQUENT REPORT OF ALTERING	CASING
NOTICE OF INTENTION TO RE-DRILL OR RI	EPAIR WELL SI	UBSEQUENT REPORT OF RE-DRILLIN	G OR REPAIR
IOTICE OF INTENTION TO SHOOT OR ACID	DIZESI	UBSEQUENT REPORT OF ABANDONM	ENT
NOTICE OF INTENTION TO PULL OR ALTER	:	UPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		onverted to Injector	x X
(INDICATE AB	!!-3	E OF REPORT, NOTICE, OR OTHER DA	
	J	anuary 18	, 19 <mark>.62</mark>
ell No. 32-24 is located	1980 ft. from (N)		$\left\{\begin{array}{c} \mathbf{E} \\ \mathbf{x} \end{array}\right\}$ line of sec. 24
NE 24	25 N 12		
(1/2 Sec. and Sec. No.)	(Twp.) (Range) San Juan	•	Mexico
(Field)	(County or Subdiv		ate or Territory)
Swahhed while runnir	na clean Point Lo	i for 15 minutes, OK ookout water (treate ng became clean, pul	d with Triton X-10
3. Ran tubing with pack	ker.		
4. Pumped 60 bbls. of fluid. Set packer a when injection star	at, and	down annulus to disp filled with inhibit	place uninhibited ed water. Will no
			EPPIN
	A	hu the Caslerias Sec. 1. f	/ RULIVEN
I understand that this plan of work must	it receive approval in writing	by the Geological Survey before op	JAN 22 1962
I understand that this plan of work must ompany Shell Oil Compar ddress P. O. Box 1200	it receive approval in writing	by the Geological Survey before op Original Sig W. M. MAI	net By COM.
D O Base 3000		Original Sig	RSHALL 3