

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SP-078064

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

-

7. UNIT AGREEMENT NAME

Carson Unit

8. FARM OR LEASE NAME

E. W. Mudge #3

9. WELL NO.

32-24

10. FIELD AND POOL, OR WILDCAT

Misti Field

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Section 25, T. 25 N.,

R. 12 W., Y.M.P.M.

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Shell Oil Company

3. ADDRESS OF OPERATOR

P.O. Box 999, Bakersfield, Calif. 93302

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface

1980' south and 1980' west of the northeast
corner of Section 25, T. 25 N., R. 12 W., N.M.P.M., San Juan
County, New Mexico.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

K.E. 6458.8, GR 6449.6

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) Set bridge plug. ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

See Attached History.



18. I hereby certify that the foregoing is true and correct

SEP 30 1968

SIGNED

John H. Shepard

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of packing of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

SHELL OIL COMPANY

RECONDITIONING
REPORTWELL NO. 32-24Sec. 24, E.W. Mudge #3
(SECTION OR LEASE)T25N, R12W, NMPM
(TOWNSHIP OR RANCHO)

Bisti

FIELD

San Juan, N.M.

COUNTY

7/18-19/1968

FROM

PERIOD

TO

DATE

REMARKS (SHOW SIZE AND TYPE TOOLS RUN)

Location: 1980' south and 1980' west of the northeast corner of Section 25,
T. 25 N., R. 12 W., NMPM, San Juan County, New Mexico

Elevation: K.B. 6458.8', Gr. 6449.6'

Total Depth: 5010', plug 5002'

Casing: 8-5/8" cemented at 107'
4-1/2" cemented at 5006', perforated 4873-4894', 4911-4930', 4941-4954',
4961-4974', and 4979-4994'

Objective: Set a wireline bridge plug

July
18

Pulled tubing and packer. Set a Baker cast iron bridge plug at 4957.5'.

19

Reran tubing with packer at 4873'. Resumed injection.

END

AFTER

CONDITION AT FIRST OF PERIOD

CONDITION BEFORE STARTING WORK
(CROSS OUT ALL BUT APPROPRIATE ITEMS)

HOLE			CASING SIZE	DEPTH SET
SIZE	FROM	TO		
			8-5/8"	107'
			4-1/2"	5006', perforations effective 4873-4894', 4911-4930' and 4941-4954'
DRILL PIPE SIZES				

DEPTH (ORIGINAL) 5010' TOP FISH (F) OR JUNK (J) 4957.5'
DEPTH LAST (RD. OR DE.) _____
DEPTH PRESENT EFFECTIVE 4957.5' BAD CSG. (C) OR LINER (L) _____

NOTE—IN ADDITION TO REPORTING ROUTINE RECONDITIONING OPERATIONS, USE THIS FORM FOR REPORTING THE FIRST INSTALLATION OF PUMPING EQUIPMENT (UNLESS WELL WAS ORIGINALLY COMPLETED ON THE PUMP), BAD CASING, FISH LEFT IN HOLE, ETC., THAT MAY OCCUR AS A RESULT OF PRODUCING OR SHUT DOWN OPERATIONS.