

X			
	20		

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe, N. M.  
Lease No. SF 078061  
Unit Carson

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 20, 1957

**Carson Unit**  
Well No. 12-20 is located 1980 ft. from [N] line and 660 ft. from [W] line of sec. 20  
SW NW 20 25N 11W R4P1  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Blair San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)  
**Kelly Bushing**

The elevation of the derrick floor above sea level is 6459.6 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

(Spudlog 6-13-57)

6-13, 14-57

Ran and cemented 200' of 8-5/8", 24.3 lb-55 casing at 210' with 190 sacks construction cement. Good cement returns to surface. Flanged up and waited on cement. Pressure tested BOP and casing with 700 psi. for 15 minutes, ok.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company  
Address 108 North Behrend Avenue  
Farmington, New Mexico

By B. W. Shepard  
B. W. Shepard  
Title Exploitation Engineer

