

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe, New Mex.

Lease No. 57 078061

Unit Carson

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING..... X
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	
Notice of Intention to Recomplete X	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 7

Carson Unit
Well No. 12-20 is located 1960 ft. from N line and 660 ft. from W line of sec. 20


20 (1/4 Sec. and Sec. No.) 25 N (Twp.) 11 W (Range) N.M.P.M. (Meridian)
21st (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the ~~bottom~~ Kelly bushing above sea level is 6460 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Status: Total Depth 5065'. **PTED 5015'**
8 5/8" casing at 210'
4 1/2" casing at 5060'
Perfor: 4892-5005' (Gross interval)
Completion Date 2-21-58



Proposed Work:

1. Sand oil re-fracture with 50,000 gal. crude oil and 1 1/2 cu. ft. 20-40 mesh sand.
2. Run production tests and establish rate.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company

Address 101 S. Behrend

Farmington, New Mexico

Original signed by
B. W. SHEPARD

By _____

Title B. W. Shepard
Exploitation Engineer