

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42 R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF-078621-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

East Bisti Unit

8. FARM OR LEASE NAME

9. WELL NO.

13

10. FIELD AND POOL, OR WILDCAT

Bisti Lower Gallup

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Section 24-25N-11W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

|   |   |
|---|---|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Water Injection  |   |
| 2. NAME OF OPERATOR<br>Skelly Oil Company   |   |
| 3. ADDRESS OF OPERATOR<br>1860 Lincoln Street-Denver, Colorado 80203  |   |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*<br>See also space 17 below.)<br>At surface<br><br>1980' FNL & 1980' FEL Section 24-25N-11W |   |
| 14. PERMIT NO.  | 15. ELEVATIONS (Show whether DF, RT, GR, etc.)<br>6510' GR 6518' DF |

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

All depths shown are from ground level

8/7/71 MI & RU Aztec Well Service Unit. No rods in hole. Spotted cement plug 5089-4889'. Pulled 2" tubing. Worked 5-1/2" casing to free same. Rigged up blue jet and perforated 1474-1475' with 4 shots. Ran 2" tubing. Spotted cement plug 1475-1325'. Pulled tubing. Shot 5-1/2" casing off at 1150'. Spotted cement plug 1200-1100'. Pulled casing up the hole. Spotted cement plug 690-590'. Pulled total of 35 jts. (1157') 5-1/2" casing.

Spotted 10' cement plug in surface casing. Installed dry hole marker. Completed P&A 8/20/71.

18. I hereby certify that the foregoing is true and correct

SIGNED

*L. L. Bipler*

TITLE

Lead Clerk

DATE

January 6, 1972

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side