

APPROVED



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYBudget Bureau 42-R358.3.
Approval expires 12-31-55.

Land Office Santa Fe, New Mexico

Lease No. 078064

Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 26, 1956

Well No. Carson 1 is located 660 ft. from [N] line and 660 ft. from [E] line of sec. 24
NE 1/4 25 N. 12 W. N.M.P. & M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Bisti San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the ~~drill hole~~ drill hole is 6230 ft. (approx. grd.)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

(Spudded 7-19-56)

7-19-56 Ran and cemented 8 5/8", 32' casing at 228' with 100 sacks treated construction cement. Good returns to surface. Finished 9:30 A.M.
7-19-56. Flanged up, installed blowout equipment. Tested blowout equipment and casing with 700 psi for 15 min., OK.

ILLECIBLE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil CompanyAddress 33 Richards StreetSalt Lake City 1, UtahBy B. E. ShepardTitle Exploitation Engineer