Form 9-331 a (Feb. 1951)

23

## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4. Form Approved,

Land Office Santa Fe, Nake

Lease No. SF-078067

Unit Carson

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	1
	Converted to Injector X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

	<u></u>	Janua	ry 29	)			
Well No. 21-23 is located	is located 660	ft. from N	line and	<b>1977.7</b> ft. fr	rom W l	ine of sec. 23	<u> </u>
No see 69	25N	124	,	NMPM	•	/agri	
(½ Sec. and Sec. No.	) (Twp.)	San Juan	)	(Meridian)	New Me	ALLIVE	
(Field)	Kelly Dumbing	(County or Subdi		r.	(State or Te	FEB1 1000	ת /
The elevation of the	der Her Hoer abov	ve sea level is  DETAILS (			10	IL CON. COM	v. /
(State names of and expecte	d depths to objective san		whis, and len	gths of proposed o	casings; indi	te mudding Bs, cer	m nt-

- 1. Pressure tested tubing with 1000 psi for 15 minutes, OK.
- Swabbed while running clean Point Lookout water (treated with Triton X-100 detergent) down easing. After tubing became clean, pulled. Bailed clean.
- 3. Ran tubing with packer.
- 4. Pumped 60 bbls. of inhibited water down annulus to displace uninhibited fluid. Set packer at 4827, and filled with inhibited water. Will notify when injection starts.

I understan	d that this plan of work must receive approval in writing	by the Geological Survey before operations may be commenced.
Company .	Shell Oil Company	
Address	P. O. Box 1200	Original Signed By
	Farmington, N.M.	Original Signed By W. M. MARSHALL  By
		Title Division Exploitation Engineer