

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe, N. M.  
Lease No. SF 078064  
Unit Carson

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	<b>X</b>
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 17, 1957


**Carson Unit**  
Well No. 14-13 is located 660 ft. from 13N line and 660 ft. from 13W line of sec. 13  
SW/4 SW/4 13 25N 13W NPM  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Risti San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6405 ft. (approx. ground)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**4-12, 13-57** Ran and cemented 213', 8-5/8", 24#, H-40 casing at 222' with 130 sacks construction cement. Good cement returns to surface. Flanged up and waited on cement. Pressure tested BOP and casing with 700 psi for 15 minutes, O.K.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SHELL OIL COMPANY  
Address 108 North Delaware Avenue  
Perkington, New Mexico  
By B. W. Shepard  
Title Exploitation Engineer

4000