



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe, N.M.
Lease No. F 078064
Unit Carson

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
Notice of Intention to Complete Well X	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 24, 1957

Carson Unit
Well No. 34-13 is located 660 ft. from S line and 1976 ft. from E line of sec. 13
13 (1/4 Sec. and Sec. No.) 25N (Twp.) 12E (Range) RMPM (Meridian)
Risti (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6421.1 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Status: Total Depth: 5100'
Casing: 8 5/8" at 218'
Hole Size: 7 7/8" from 218 - Total Depth

Proposed Work:

1. Run and cement 4 1/2" casing at 5096' with 200 sacks. Displace with oil.
2. Clean out to 5060'.
3. Perforate four 1/2" holes/ft select intervals between 4800-5050.
4. If applicable, sand oil fracture with 30,000 gal. crude and 45,000 gal. sand.
5. Swab well into production and establish initial rate.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company
Address 108 North Behrend
Farmington, New Mexico

By B. W. Shepard
Title S. E. Shepard
Exploitation Engineer



