NEW MEXICO

Shelloil Co

| BISTI | CARSO | Unit | (PDET | 1330 | Test | 4½" c

CARSON UNIT
Unit 34X-13 (#200)
(PDET)
1330' Pictured Cliffs
Test
4½" csg @ 1324'

C-13-25-N-12W RECEIVED

FEB 19 1974

OIL CON. COM.
DIST. 3 TD 1330. PB 1272. (RRD 7/2/73). WEL ... JGED AND ABANDONED. MI Halliburton and plugged well as follows: Interval Sx Cmt Type Cmt Reg cmt w/2% CaCl2 & 1/4#/sk Flocele 20 1024-1275 Reg cmt w/2% CaCl2 & 1/4#/sk Flocele 10 5-100 Cut off csg 5' below GL. Installed dry hole marker 3' into 4½" csg and welded plate around marker and top of Released Hal. P&A complete @ 7 PM, 2/12/74. 8-5/8" csg. Released Ha Elev: 6419 KB, 6408 GL. Log Top: PICTURED CLIFFS SS 1231' (+5188)
This exploratory test encountered 18' net sandstone in the objective Pictured Cliffs w/8' exhibiting greater than 20% porosity and a calculated maximum  $S_g$  of 61%. Completion attempts, after fracture treatment, failed to establish gas production; however, tracer survey suggests fractured treatment below objective. Further evaluation by drilling an additional well is being considered. FEB 14 1974 FINAL REPORT.