



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe, N.M.
Lease No. SP 078061
Unit Carson

RECEIVED

AUG 8 1957

FARMINGTON, NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	X
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 6, 19 57

Well No. 14-17 is located 660 ft. from 17N line and 640 ft. from 17W line of sec. 17
SW 17 25N 11W RMPM
 (¼ Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Bisti San Juan New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation ~~at the bottom of the well~~ is 6423 ft. (Approx. ground)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

(Spudded 7-31-57)

7-31, 8-1-57 Ran and cemented 8-5/8", 24', J-55 casing at 173' with 130 sacks treated cement. Good returns to surface. Flanged up and waited on cement. Pressure tested BOP and casing with 700 psi. for 15 minutes, OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company
 Address 101 South Behrend
Farmington, New Mexico

By B. W. Shepard
 Title Exploitation Engineer

