

3-25-68

Shell Oil Company

WELLS REQUIRING FILE CORRECTION ONLY

LEASE NAME & WELL NUMBER	LOCATION	POOL	PRESENT ACREAGE	CORRECT ACREAGE
Carson Unit #3	L-7-25N-11W	Bisti Gallup	80 (N/2 SW/4)	80.11 ✓
Carson Unit #24-7	N-7-25N-11W	Bisti Gallup	80 (S/2 SW/4)	80.25 ✓
Carson Unit #21-18	C-18-25N-11W	Bisti Gallup	80(N/2 NW/4)	80.35 ✓
Carson Unit #12-18	(E-18-25N-11W	Bisti Gallup	80 (S/2 NW/4)	80.42 ✓
Joint	(			
Carson Unit #22-18	(F-18-25N-11W	Bisti Gallup	80 (S/2 NW/4)	80.42 ✓
Carson Unit #23-18	(K-18-25N-11W	Bisti Gallup	80 (N/2 SW/4)	80.50 ✓
Joint	(			
Carson Unit #13-18	(L-18-25N-11W	Bisti Gallup	80 (N/2 SW/4)	80.50 ✓
Carson Unit #14-18	(M-18-25N-11W	Bisti Gallup	80 (S/2 SW/4)	80.57 ✓
Joint	(			
Carson Unit #24-18	(N-18-25N-11W	Bisti Gallup	80 (S/2 SW/4)	80.57 ✓
Carson Unit #21-19	(C-19-25N-11W	Bisti Gallup	80 (N/2 NW/4)	80.56 ✓
Joint	(			
Carson Unit #11-19	(D-19-25N-11W	Bisti Gallup	40 (N/2 NW/4)	80.56 ✓
Carson Unit #12-19	(E-19-25N-11W	Bisti Gallup	80 (S/2 NW/4)	80.47 ✓
Joint	(			
Carson Unit #22-19	(F-19-25N-11W	Bisti Gallup	80 (S/2 NW/4)	80.47 ✓
Carson Unit #23-19	K-19-25N-11W	Bisti Gallup	80 (N/2 SW/4)	80.37 ✓
Carson Unit #11-30	D-30-25N-11W	Bisti Gallup	80 (N/2 NW/4)	80.25 ✓

*Ch. 6
note 6-10-68
on Unit #3*