

Form 9-521a
(Feb. 1961)

		17		

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **ST 078062**
Lease No. **Carson Unit**
Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL
NOTICE OF INTENTION TO CHANGE PLANS
NOTICE OF INTENTION TO TEST WATER SHUT-OFF
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL
NOTICE OF INTENTION TO SHOOT OR ACIDIZE
NOTICE OF INTENTION TO PULL OR ALTER CASING
NOTICE OF INTENTION TO ABANDON WELL

SUBSEQUENT REPORT OF WATER SHUT-OFF
SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
SUBSEQUENT REPORT OF ALTERING CASING
SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
SUBSEQUENT REPORT OF ABANDONMENT
SUPPLEMENTARY WELL HISTORY

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. **Carson Unit 44-17** is located **710** ft. from **N** line and **710** ft. from **E** line of sec. **17**
25N (Twp.) **11W** (Range) **MMW** (Meridian) **New Mexico** (State or Territory)
San Juan (County or Subdivision)
17 (Field)

The elevation of the derrick floor above sea level is **6424** ft. (approx. ground)
DETAILS OF WORK
(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

- Proposed Work**
1. Drill 12-1/4" hole to 100'.
 2. Cement 8-5/8", 240', J-55 casing at 100' with 100 sacks cement (circulated).
 3. Drill 7-7/8" hole to 5060' (objective - Gallup).
 4. Cement 4-1/2", 9.50', J-55 casing at 5060' with 150 sacks cement.
 5. Perforate four 1/2" holes/ft. selected intervals between 4920' and 5030'.
 6. Sand oil fracture with 50,000 gal. crude, 1/2 gal. sand.
 7. Recover load and free oil, establish initial rate.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Shell Oil Company**
Address **Post Office Box 158**
Farmington, New Mexico

Original signed by
R. S. Mac ALISTER, JR.
By **R. S. Mac Alister, Jr.**
Title **Division Exploitation**



Well Location and Acreage Dedication Plat

Section A.

Operator **SHELL OIL COMPANY** Date **Oct. 13, 1959**
 Well No. **44-17** Unit Letter **P** Section **17** Lease **Carson Unit**
 Located **710** Feet From **THE SOUTH** Line **710** Township **25 NORTH** Range **11 WEST** NADOM
 County **SAN JUAN** G. L. Elevation **6423.7** Feet From **THE EAST** Line **40** Date
 Name of Producing Formation **Gallup** Dedicated Acreage **40** Acre
 Plat **Bisti**

1. Is the Operator the only owner in the dedicated acreage outlined on this plat below?
 Yes **X** No
2. If the answer to question one is "no", have the interests of all the owners been consolidated by communitization agreement or otherwise? Yes No If answer is "yes", Type of Consolidation
3. If the answer to question two is "no", list all the owners and their respective interests below:

Owner

Land Description



Section B.

Note: All distances must be from outer boundaries of section.

This is to certify that the information in Section A above is true and complete to the best of my knowledge and belief.

Shell Oil Company



(Operator)

Original signed by
R. S. Mac ALISTER, JR.

P.O. Box 158

Farmington, New Mexico

REF. GLO Plat dated. 11 June 1934
 T.B.M. Iron pin 204' S 81° E of
 Location. Elev. 6434.95



Farmington, New Mexico

This is to certify that the above plat was prepared from field notes of actual surveys made by me or under my supervision and that the same are true and correct to the best of my knowledge and belief.

Date Surveyed 12 DECEMBER 1958

James P. Leese
 Registered Professional Engineer and/or Land Surveyor
 JAMES P. LEESE NEW MEXICO REG. NO. 1463