

(SUBMIT IN TRIPLICATE)

Indian Agency - ~~_____~~

UNITED STATES

Table 1

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee -----

Lease No. **14-20-503-1433**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<div style="text-align: center;"> </div>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OF WELL	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 10, 1958

Navajo Allottees "O"

Well No. 1 is located 660 ft. from S line and 1900 ft. from E line of sec. 15

SE of Sec. 15
(1/4 Sec. and Sec. No.)

25-11
(TWD.)

11-3
(Range)

NMPM
(Meridian)

Results

(Field)

Figure 1

(County or Subdivision)

New Ideas

(State or Territory)

The elevation of the derrick floor above sea level is 6401 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate additional casing points, and all other important proposed work)

Spudded 6:30 A.M., March 20, 1958.

Drilled 12-1/4" hole to 330' and cemented 281' of 9-5/8" O.D. casing at 293' with 300 sacks cement. Cement circulated. Tested casing with 800# pressure for 30 minutes. Tested Ok.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Texas Company

Address Box 117

Farmington, New Mexico

By

Title District Superintendent

