Form 9-331 a (Feb. 1951)

1 6

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Budget Bureau No. 42-R358.4. Form Approved.		
Land Office	Santa Fa, L.	
Lease No	M=030253	
Unit	Careon	

SUNDRY NOTICES AND REPORTS ON WELLS

<u></u>	
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING.
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
otice of Conversion to injector 1	
(INDICATE ABOVE BY CHECK MARK N	ATURE OF REPORT, NOTICE, OR OTHER DATA)
-	, 1962
Well No. 14-1 is located ft. from	$\begin{Bmatrix} \mathbf{N} \\ \mathbf{S} \end{Bmatrix}$ line and 420 ft. from $\begin{Bmatrix} \mathbf{E} \\ \mathbf{W} \end{Bmatrix}$ line of sec. 16
(½ Sec. and Sec. No.) (Twp.)	ange) (Meridian)
(Field) (County or S	Subdivision) (State of Perritory)
The elevation of the gerral sear above sea leve	DEC 1 0 1962
DETAIL	S OF WORK
(State names of and expected depths to objective sands; show sizes,	weights, and lengths of proposed casings; indicate mudding jobs, cementer important proposed work)
ing points, and all oth	er important proposed work)
Status: ID 5005'; Coming 6-5/6" at 211' 4004', 5024'-5032', 5043'-5052' Proposed Work:	, 4-1/2" at 5002'; seria. 1079'-00', 1970'-
1. Pressure test tubing with 1000 psi	for 15 min.
2. Pull tubing and bail clean.	www.moo.moo.w
3. Run 2-3/8" open-ended tubing to both	tom and swab while running clean Point Look-
out water (treated with Triton X-100	O detergent) down casing. When fluid cleans
up. pull tubing.	
4. Run 2-3/8" tubing with packer ten fe	eet above perforations.
5. Dump 60 bbls. of inhibited water do	wn annulus to displace uninhibited fluid. Se
packer and fill with inhibited water	
6. Run pressure and temperature survey	
	riting by the Geological Survey before operations may be commenced.
Company Leli Ci Company	
Address 1200	Original signed by
	H. D. ENGLISH
	Ву
	B. D. Highlish
***************************************	Title system to led to the manner