

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **078078**
Unit **Harvey**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 14th, 19 57

Well No. **1** is located **760** ft. from **N** line and **1880** ft. from **E** line of sec. **14**

SW/4 SE/4 Sec. 14
(¼ Sec. and Sec. No.)


25N
(Twp.)

11W
(Range)

N.M.P.M.
(Meridian)

Wildcat
(Field)

San Juan
(County or Subdivision)



The elevation of the derrick floor above sea level is **6542** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed plugs; indicate mudding jobs, cementing points, and all other important proposed work.)

1-16-57 TD 5200'. Spotted cement plugs as follows:

40 sacks from 4870' to 5200'
30 sacks from 3800' to 3900'
30 sacks from 2150' to 2250'
30 sacks from 1350' to 1450'

5 sacks in base of 8-5/8" casing and 10 sacks in top of 8-5/8" casing, which was left in the hole.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **BENSON-MONTIN-OREER DRILLING CORP.**

Address **405½ West Broadway**

Farmington, New Mexico

By

Title **Vice-President**