



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 078630  
Unit Foster

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 18th, 1956

Well No. 1 is located 1780 ft. from N line and 1190 ft. from E line of sec. 13

NW/4 SW/4 Sec. 13      25N      8W      N. M. P. M.  
(1/4 Sec. and Sec. No.)      (Twp.)      (Range)      (Meridian)  
Ballard      San Juan      New Mexico  
(Field)      (County or Subdivision)      (State or Territory)

The elevation of the derrick floor above sea level is 6975 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

- 7-25-56 TD 2691' RKB. Set 15 joints 485' of 5-1/2" OD 15.5# J-55 casing and 69 joints 2197' of 5-1/2" OD 14# J-55 casing at 2652' RKB with 100 sacks cement.
- 7-27-56 Pressured up on casing to 1000#. No pressure decrease in one hour.
- 7-28-56 Cleaned out to total depth 2691'. 3-hour test showed no water.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company PETRO-ATLAS CORPORATION

Address 7th Floor, Simms Building

Albuquerque, New Mexico

By Tom Boland

Title President

