

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or reenter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED
OMB No. 1004-0135
Expires July 31, 1996

5. Lease Serial No.

NMSF-078061

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

Carson Unit

8. Well Name and No.

Carson Unit 17 #43

9. API Well No.

30-045-05366

10. Field and Pool, or Exploratory Area

Bisti Lower Gallup

11. County or Parish, State

San Juan, NM

SUBMIT IN TRIPLICATE – Other instructions on reverse side

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Elm Ridge Resources, Inc.

3a. Address

PO Box 189 Farmington, NM 87499

3b. Phone No. (include area code)

505-632-3476

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1880' FSL & 660' FEL

Sec. 17-T25N- R11W

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize <input type="checkbox"/> Deepen <input type="checkbox"/> Production (Start/Resume) <input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing <input type="checkbox"/> Fracture Treat <input type="checkbox"/> Reclamation <input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair <input type="checkbox"/> New Construction <input type="checkbox"/> Recomplete <input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans <input checked="" type="checkbox"/> Plug and Abandon <input type="checkbox"/> Temporarily Abandon
	<input type="checkbox"/> Convert to Injection <input type="checkbox"/> Plug Back <input type="checkbox"/> Water Disposal

13. Describe Proposed or Completed Operations (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once Testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Elm Ridge Resources Inc plug & abandoned the Carson Unit 17 #43 on Monday, April 29, 2002 as follows:
See Attachment

Certified Return Receipt # 7001 0320 0002 6707 0760

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Trudy Grubelnik

Title

Production Technician

Signature

Date

May 3, 2002

THIS SPACE FOR FEDERAL OR STATE USE

Approved by

Title

ACCEPTED FOR RECORD

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

MAY 29 2002

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**Elm Ridge Resources Inc.
Plug And Abandon Report**

Operator: **Elm Ridge Resources, Inc.**
Date: May 2, 2002
Field: Lower Gallup
Contractor: Triple P
Supervisor: Doug Endsley

Well Name: Carson Unit 17 #43
Internal Well No.:
Report No.: 2 and 3
Location: Sec. 17, T25N, R11W
Foreman: Tim Duggan

Work Summary:

Monday, April 29, 2002 : MIRU Triple P Rig # 12. Release packer - pull 35,000#'s, 12,000 #'s over tubing string. First 40-joints - got tight work up and down. Pull 20 more joints tubing - free up TOH - lay down 135-joints. Stand back 20-joints - tally tubing.

Tuesday, April 30, 2002: P/U tubing. TIH w/4-1/2 bit and scrapper to 4965. 134-joints 2-1/16 and 20-joints 2-3/8. TOH. TIH w/4-1/2 CIBP set @ 4964'. Roll hole w/85 bbls produced water. Pump 5.9 bbls 28 sx Class B, 15.6 PPG - cement 1-3/4 BPM @ 850 PSI. Displace w/14.0 bbls, 2 BPM @ 900 Psi. TOH 15-stands. SDON.

Wednesday, May 1, 2002: TIH - tag cement 11-joints out @ 4623'. TOH - RIH w/wireline - perf 3-shots @ 2080'. POH. TIH w-4-1/2 retainer set 2 2039'. Load hole - pressure test to 500 PSI - okay. Establish rate 1 BPM @ 800 PSI. Pump 10.7 bbls 51 sx Class "B", 15.6 PPG, 1 BPM @ 800 PSI (7 bbls into pumping cement - pressure dropped to 200 PSI. Circulate up casing while stung into retainer. Finish pumping 3.7 bbls). Displace w/4.3 bbl, 1-1/2 BPM - stopped circulation. Pressure back up to 800 PSI. TOH to 1326'. Roll hole w/24 bbls. TOH. RIH w/wireline - perf 3-shots @ 1324'. TIH w/4-1/2 retainer set @ 1262'. Pressure test to 500 PSI - okay. Pump 10.7 bbls, 51 sx Class "B", 15.6 PPG, 1 BPM @ 800 PSI. Displace w/2.4 bbl, 1 BPM @ 800 PSI. TOH. RIH w/wireline - perf 3-shots @ 1050. POH. TIH w/4-1/2 retainer set @ 1003. Load hole - pump 10.7 bbls 51 sx Class "B", 1-3/4 BPM @ 700 PSI. Displace w/1.3 bbl @ 800 PSI. TOH - laying down. RIH w/wireline - perf 3-shots @ 489'. Pump 22 bbl water down casing @ 400 PSI - not circulating. Pump 5 bbl down surface, 3 BPM @ 50 PSI. Pump down casing 37.4 bbl 178 sx Class "B", 15.6 PPG, 1-1/2 BPM @ 200 PSI. Circulate cement to surface. ND BOP.