


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe, N.M.
Lease No. SF 978066
Unit Carson



SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED
FEB 14 1958
GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 11, 1958

Carson Unit

Well No. 43-18 is located 1980 ft. from N line and 660 ft. from E line of sec. 18

SE 18
(¼ Sec. and Sec. No.)

25N
(Twp.)

11W
(Range)

10PM
(Meridian)

S1st1
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation at the surface of the well is 6634 ft. (Approx. ground)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mud logging, cementing points, and all other important proposed work)

(Spudded 2-5-58)

2-5, 9-58 Ran and cemented 6-5/8" 24#, J-55 casing at 111' with 100 sacks treated cement. Good returns to surface. Flanged up and waited on cement. Tested 500 psi casing with 700 PSI 15 min. OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Stall Oil Company

Address 101 S. Behrend

Farmington, New Mexico

By H. W. Shepard
Title Exploitation Engineer