Form 9-331 a (Feb. 1951)	ŧ
-----------------------------	---

1		Ì	
1			
1			
1			. !
1		i	
		!	
1	!	:	! I

## (SUBMIT IN TRIPLICATE)

## UNITED STATES

Land Office	
Lease No	<i>- 7</i> 8977

SUNDR	DEPARTMENT GEOLOG	OF THE INTERIOR GICAL SURVEY	Unit WELLS	18.19 18.20 18.19 18.20 18.20
NOTICE OF INTENTION TO DRILL NOTICE OF INTENTION TO CHANG NOTICE OF INTENTION TO RE-DE NOTICE OF INTENTION TO SHOOT NOTICE OF INTENTION TO PULL NOTICE OF INTENTION TO ABANG	GE PLANS WATER SHUT-OFF RILL OR REPAIR WELL T OR ACIDIZE OR ALTER CASING	<u> </u>	ING OR ACIDIZING NG CASINGLLING OR REPAIR DOMENT	- <del>1</del>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

			4.3	, 19.53
Well No.1 is loca	w ited <u>1980</u> ft.	from $\begin{bmatrix} \mathbf{M} \\ \mathbf{S} \end{bmatrix}$ line	and <u>660</u> ft. from ${}^{\mathrm{H}}_{\mathrm{N}}$	line of sec. 14
(W Sec. and Sec. No.)	125%	10	(Meridian)	Company of the second of the s
ilicat (Field)		bunty or Subdivision)	(State	
The elevation of the derric				ALCON CO
	DE	ETAILS OF W	ORK	Jun grow Com

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Cleaned well out to 6604'. Sen 5%" cag. to T.D. and camented with 400 sa of Pozaia cement. Ther shut off on. Perforated 0500 to 0560 and 6442 to 6486 with 4 shots per ft. Sand-oil fractures with 1500 bbls oil & 20,000 sand. Sasbbed well for 15 days. Well had slight show of gas but was costly water. Equae od perfs from 6520 to 6500. de-fracked top perfs. Well showed all apter. Lecided to try to pull cag and plug and abandon. Top of cement on 5%" cag. was 1340' according to temperature survey.

I understand that this plan of work must receive approval in writing by the	Geological Survey before operations may be commenced.
Company 3	
Address Room 337 W. C. Retional Dank Blug	
ionvar 2, Colorado	By January Title Goods ist
	Title Coplosist
	GPO 918507