	_		
1	ĺ	1	
I	ļ 		
1			
ļ			
1			
L			

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Canta Pe
Lease No.	V15524
Unit	i'ayne 🦸

SUNDRY NOTICES AND REPORTS ONEWELLS E

		N P
NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF 1301
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.		
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.		SUBSECUENT REPORT OF RE-DRILLING OBCHEPAIR NEW THE X100
NOTICE OF INTENTION TO PULL OR ALTER CASING.		SUBSEQUENT REPORT OF RE-DRILLING GROWEN HEN MEXICO SUBSEQUENT REPORT OF ABANDON HEN LIGHTON, WELL HISTORY SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL.		SUPPLEMENTARY WELL HISTORY
THE STATE OF THE ABANDON WELL.		4
Well No. 4 is located 2450 ft. fro		FURE OF REPORT, NOTICE, OR OTHER DATA) 10
(3/ Sec. and Sec. No.) (Twp.)	(Rang	~ (w)
((1001)	
Ballard Cliffs (Coun	ty or Sub	odivision) (State or Territory)
 Determine 5 1/2" casing free p Spot a 100' cement plug across If 5 1/2" casing is cut below 	Ø5 - oist cut-	2309' to cover open hole (2359-2305') and cut.
(1200-133 [©] ').		
5. Spot a 20' coment plug with a of surface pipe. 6. Clean location.	4' x	" personent type dry hole parter by UL1 7 1961
I understand that this plan of work must receive approval Company Company	in writin	ng by the Geological Survey before operations may be commenced.
Address Box 990		
Parmington, New Mexico	-	By Original Signed R. G. MILLER
	-	Title Petroleum Engineer
P*************************************	- ,	litle