



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe, New Mexico
Lease No. SF-078067
Unit Carson Unit

SUNDRY NOTICES AND REPORTS ON WELLS

| | | |
|------------------------------------------------|--------------------------------------------|---|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF | X |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING | |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING | |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR | |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT | |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY | |
| NOTICE OF INTENTION TO ABANDON WELL | | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 6, 1961

Water Well

Well No. W-3 is located 2553 ft. from N line and 2325 ft. from E line of sec. 14

SW NE Section 14 T 25 N R 12 W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Disti San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

Kelly Dushing

The elevation of the ~~drill hole~~ drill hole above sea level is 6411 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

6-24-61 Ran and cemented 7", J-55, 23# casing at 3844' (3845 TD) with 275 ex. cement treated with 20% Biscol D and 2% calcium chloride. Flanged up. Tested casing with 1500 psi. OK.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company

Address P. O. Box 1200

Farmington, N.M.

Original Signed By
W. M. MARSHALL

By W. M. Marshall
Title Division Exploitation Engineer