

X	18		

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Navajo

Allottee Alotted

Lease No. 14-20-603-1283
1284

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	X	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL		

RECEIVED
MAR 7 1958
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 12-18 is located 2000 ft. from N line and 660 ft. from W line of sec. 18
Carson Unit

18 (1/4 Sec. and Sec. No.) 25N (Twp.) 11W (Range) RMPN (Meridian)
Monte (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of ~~the ground surface~~ is 6367 ft. (approx. ground).

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Proposed Work:

1. Drill 12-1/4 hole to 100'.
2. Cement 8-5/8" casing at 100', with 90 sacks construction cement.
3. Drill 7-7/8" hole to 3020'.
4. Cement 4-1/2" casing at 3020' with 150 sacks construction cement.
5. Perforate four 1/2" holes/ft. at intervals determined by logs.
6. Sand-oil fracter if applicable.
7. Swab well into production and establish rate.

RECEIVED
MAR 10 1958
OIL CON. COM.
DIST. 3

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company
Address 101 South Behrend
Farmington, New Mexico

By B. W. Robinson
B. W. Shepard
Title Exploitation Engineer



NEW MEXICO OIL CONSERVATION COMMISSION

Well Location and Acreage Dedication Plat

Section A.

Date March 3, 1958Operator SHELL OIL COMPANYLease Carson Unit Allotted Land 14-20-603-1284Well No. 12-18 Unit Letter E Section 18Located 2080 Feet From the NORTH Line, 660County SAN JUAN G. L. Elevation 6366.9Name of Producing Formation GallupTownship 25 NORTH Range 11 WEST, N.M.P.M.Feet From the WEST, 1100Dedicated Acreage 80.42Pool Bisti

1. Is the Operator the only owner in the dedicated acreage outlined on the plat below?

Yes ☐ No ☒2. If the answer to question one is "no", have the interests of all the owners been consolidated by agreement or otherwise? Yes ☒ No ☐ If answer is "yes", Type of Consolidation:Carson Unit

3. If the answer to question two is "no", list all the owners and their respective interests below.

Owner

Lease Description

Section B.

This is to certify that the information in Section A above is true and complete to the best of my knowledge and belief.

Shell Oil Company

Operator:

E. B. Robinson
(Representative)


101 South Behrend

(Address)

Farmington, New Mexico

Note: All distances must be from outer boundary of section.

Sec. Cor.



0 330 660 990 1320 1650 1980 2310 2640 2970 3300

Scale: 1 inch equals 1 mile

Ref: GLO plat dated 11 June 1934

TM: Iron rod 223' N 60° E of Location.
Elev. 6367.78



Farmington, New Mexico

RECEIVED
MAR 7 1958
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

RECEIVED
MAR 10 1958
OIL CON. COM.
DIST. 3

This is to certify that the above plat was prepared from the notes of a survey made by me or under my supervision and that the same are true and correct to the best of my knowledge and belief.

Date Surveyed 27 FEBRUARY 1958

James P. Luse
Registered Professional Engineer

3-25-68

Shell Oil Company

WELLS REQUIRING FILE CORRECTION ONLY

LEASE NAME & WELL NUMBER	LOCATION	POOL	PRESENT ACREAGE	CORRECT ACREAGE
Carson Unit #3	L-7-25N-11W	Bisti Gallup	80 (N/2 SW/4)	80.11 ✓
Carson Unit #24-7	N-7-25N-11W	Bisti Gallup	80 (S/2 SW/4)	80.25 ✓
Carson Unit #21-18	C-18-25N-11W	Bisti Gallup	80(N/2 NW/4)	80.35 ✓
Carson Unit #12-18	(E-18-25N-11W	Bisti Gallup	80 (S/2 NW/4)	80.42 ✓
	Joint			
Carson Unit #22-18	(F-18-25N-11W	Bisti Gallup	80 (S/2 NW/4)	80.42 ✓
Carson Unit #23-18	(K-18-25N-11W	Bisti Gallup	80 (N/2 SW/4)	80.50 ✓
Carson Unit #13-18	(L-18-25N-11W	Bisti Gallup	80 (N/2 SW/4)	80.50 ✓
Carson Unit #14-18	(M-18-25N-11W	Bisti Gallup	80 (S/2 SW/4)	80.57 ✓
Carson Unit #24-18	(N-18-25N-11W	Bisti Gallup	80 (S/2 SW/4)	80.57 ✓
Carson Unit #21-19	(C-19-25N-11W	Bisti Gallup	80 (N/2 NW/4)	80.56 ✓
Carson Unit #11-19	(D-19-25N-11W	Bisti Gallup	40 (N/2 NW/4)	80.56 ✓
Carson Unit #12-19	(E-19-25N-11W	Bisti Gallup	80 (S/2 NW/4)	80.47 ✓
Carson Unit #22-19	(F-19-25N-11W	Bisti Gallup	80 (S/2 NW/4)	80.47 ✓
Carson Unit #23-19	K-19-25N-11W	Bisti Gallup	80 (N/2 SW/4)	80.37 ✓
Carson Unit #11-30	D-30-25N-11W	Bisti Gallup	80 (N/2 NW/4)	80.25 ✓

*Ch. 6
note 6 survey
on Unit #3*