## SHELL OIL COMPANY

Carson Unit 22-14

Bisti		
	(FIELD)	

San Juan, New Mexico (county)

## DRILLING REPORT FOR PERIOD ENDING

	14	
	(SECTION OR LEASE)	_
25N	12W	
	(TOWNSHIP OR RANCHO)	_

DAY	DEPTHS		REMARKS		
	FROM	то	, , , , , , , , , , , , , , , , , , ,		
			Location: 2070°S, and 1980°E of NW Corner, Sec. 14, T25N, R12W, NMPM, San Juan County, New Mexico.		
			Elevations: KB 6307.7° DF 6306.9° GR 6298.4°		
2-7 to 2-8	0	2575	Spudded 8:30 A.M. 2-7-60. Ran and cemented (99°) 8 5/8°, 28#, J-55 Casing at 108° with 100 sacks cement treated with 2% calcium chloride, good returns to surface. Pressure tested casing and BOP with 700 psi, OK.		
2-9 to 2-12	2575	4771	Drilled 21961		
2-13	4771	4824	Cored 53! Core #1 4771-4824 Recovered 53!.		
2 1/	1901				
2-14	4824	4930	<u>Drilled 106</u> <sup>1</sup> . Ran Induction and Gamma Ray-Sonic logs.		
2-15	4930 (TD)		Ran and cemented (4918) 4 1/2", 9.5# J-55 casing at 4927 with 150 sacks cement treated with 4% gel. Displaced with oil, held 1500 psi, OK. Released rig 10:00 A.M. 2-15-60.		
			Checked BOP daily Oil Base Mud Summary: WT 8.4 - 8.5 #/gal. VIS 114 - 154 ses.		
			Contractor: Brinkerhoff Drilling Co. Co. Pusher: C. L. Christiansen  APR 25 1961  OIL CON. DIST		

HOLE			CASING SIZE	DEPTH SET
IZK	FROM	то		
			1	
	1		-	
	PIPE			