SHELL OIL COMPANY

Carson Unit 12-14

Bisti (FIELD)

DRILLING REPORT FOR PERIOD ENDING

14 (SECTION OR LEASE) T 25 N. R 12 W

San Juan, New Mexico

9-23-57

Dan Ju	(COUNT	W MEXICO	(TOWNSHIP OR RANGHO)	
day 57	DEPTHS		REMARKS	
	FROM	то	RAMARRA	
			Location: 1960'S and 612.7 E of NW Corner Sec 14, T 25 N, R 12 W, NMPM, San Juan County, New Mexico	
			Elevations DF 6236.9 GR 6229.8 KB 6238.1	
9-14 to 9-15	<u>.</u>	1534	Spudded 9:00 A M 9-14-57. Ran and cemented (96') 8 5/8", 24#, J-55, Span casing at 105' with 85 sacks cement treated with 2% calcium chloride. Good returns to surface. Flanged up and waited on cement. Pressure tested casing and BOP with 500 psi for 30 minutes, 0K. Drilled. Twisted kelly off while drilling at 1159', recovered with overshot.	
9-16 to 9-21	1534	4665	Drilled 3131'.	
9-22 to 9-23	4665	4864	Drilled 199%. Ran Electrical Survey and Microlog. Ran and cemented (4850) 4 1/2, 9.5# casing at 4859 with 150 sacks cement treated with 4% gel, final pressure 1500 psi. Displaced with oil. Released rig 11:00 A M 9-23-57.	
			Checked BOP daily	
			Mud Summary Wt 9.2-9.9 #/gal Vis 50-100 sec WL 3.8-8 cc FC 2/32"	
			Contractor: Brinkerhoff Drilling Company	
	CONDITION AT BEGINNING OF PERIOD Drillers 8 G. M. Benton			

HOLE DEPTH SET CASING SIZE SIZE FROM TO DRILL PIPE

R. C. Cary

M. D. Schulze

