

SHELL OIL COMPANY

Carson Unit 12-14

WELL NO.

Bisti

(FIELD)

San Juan, New Mexico

(COUNTY)

DRILLING REPORT

FOR PERIOD ENDING

9-29-57

14

(SECTION OR LEASE)

T 25 N. R 12 W

(TOWNSHIP OR RANGHO)

DAY 57	DEPTHS		REMARKS
	FROM	TO	
9-24	4864	TD	Ran Gamma Ray-Collar log. Perforated four 1/2" bullet holes/ft 4723-37, 4786-93, 4800-10, 4816-26.
9-25			Ran tubing to 4728'. Swabbed 2 hours, recovered 40 bbls, well started to flow.
9-26			Flowed 3 hours, 50 bbl gross (398 B/D), 64/64" bean
9-27			Flowed 6 hours, 124 bbl gross (494 B/D), 64/64" bean, TP 40, CP 40
9-28			Flowed 4 hours, 145 Bbl gross (869 B/D), cut 0.1%, 64/64" bean, TP 60, CP 100
9-29			INITIAL PRODUCTION Flowing, 608 B/D gross, 607 B/D clean, cut 0.1%, 64/64" bean, 333 MCF/D, GOR 550, TP 60, CP 330. Completed 9-29-57.

CONDITION AT BEGINNING OF PERIOD

HOLE			CASING SIZE	DEPTH SET
SIZE	FROM	TO		
12 1/4"	0	105	8 5/8"	105'
7 7/8"	105	4864	4 1/2"	4859'
DRILL PIPE SIZES			4 1/2"	

E. B. JOHNSTONE