

## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Bu Ap	lget Bureau No. 42–R358.4. proval expires 12–31–60.
Land Office	Santa Po, Y. M.
Lease No	ST 078067
**	Carpon

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INT	TENTION TO DRILL		SUBSEQUENT REPOR	T OF WATER SHUT-OF	F	
NOTICE OF INT	TENTION TO CHANGE PLANS		SUBSEQUENT REPOR	T OF SHOOTING OR A	CIDIZING	
NOTICE OF INT	TENTION TO TEST WATER SHU	JT-0FF	SUBSEQUENT REPOR	T OF ALTERING CASIN	G	
NOTICE OF INT	TENTION TO RE-DRILL OR RE	PAIR WELL	SUBSEQUENT REPOR	T OF RE-DRILLING OR	REPAIR	
NOTICE OF INT	TENTION TO SHOOT OR ACIDI	ZE	SUBSEQUENT REPOR	T OF ABANDONMENT		
	TENTION TO PULL OR ALTER		SUPPLEMENTARY WE	LL HISTORY		
	tention to abandon well.  Tintention to Ge					
	(INDICATE ABO	VE BY CHECK MARK NAT	URE OF REPORT, NOTIC	E, OR OTHER DATA)		
				May 8		19 57
_						19.5.1.
Well No.	32-14 is located	1960 ft. from.	$\left\{\begin{array}{c} N \\ S \end{array}\right\}$ line and	ft. from E	line of sec	14
SW HE	14	25 <b>N</b> 12	i me	X		
(1/4 Sec.	and Sec. No.)	(Twp.) (Ran	ge) (	Meridian)	1 am	
<u> Noti</u>	(Field)	(County or Sui	ndivision)	(State or	Territory)	
,	Kelly Bunk		our blody	(50800 01	Tellioly	
The elevation	on of the harinkeles	r above sea level	is <b>6403</b> ft.			
		DETAILS	OF WORK			
(State names of	and expected depths to objec i	tive sands; show sizes, w ing points, and all other	eights, and lengths of important proposed v	proposed casings; ind vork)	icate mudeling	HHV
••		000 I			/ / "	-nrist(f)/
Plates:	Total Depth: 5				. MÀ∖	7 13 was
	Coming: 8-5/8" Hele Size: 7-7	#6 417 /## from 2171	to T.D.		lon	****
	MATERIAL I	, 0 2200 011	00 2000		1	COM.
Presented	Marks				- A &	75T. 3
1.		4-1/2" cening		h 200 secks	ecostructio	m commt.
2.	If plug above 5	GAS', elean or	t.			<b>:</b>
3.	Perforate four	1/2" holes so	LOGI LINGETURI	s parkeans to	AND BURE 4707	-24/m1
4.	If applicable,	badgaatjar sug	ere eren joge	office work	etian veta	
7•	Saltin metry yares	beneather on		TO THE PARTY		,
I understand	l that this plan of work must	receive approval in writ	ing by the Geological	Survey before operati	ons may be comme	nced.
Company	SHIELL OIL COMPA	NY				
Company						
Address	108 North Bahre	and Avenue				
		. Marrie a.a.	<b>5</b>	Blad 80.		
	tetarities, me		Ву	BW She	mi	
			Tial.	Registati	n Bariner	
			Title			