14

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land	Office	. 51	inte	Fe,	光。 组
Loaso	No.	SP	0780	% 7	
Unit _	Ç	urec	211		

SUNDRY NOTICES AND REPORTS ON WELLS

					,220		
NOTICE (OF INTENTION TO DRILL		SUBSEQUENT R	EPORT OF WATER SHUT-OFF			
NOTICE OF INTENTION TO CHANGE PLANS		PLANS	SUBSEQUENT R	EPORT OF SHOOTING OR AC	IDIZING		
		SUBSEQUENT R	EPORT OF ALTERING CASING	j			
NOTICE (OF INTENTION TO RE-DRILL	OR REPAIR WELL	SUBSEQUENT R	EPORT OF RE-DRILLING OR	REPAIR		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.			SUBSEQUENT R	SUBSEQUENT REPORT OF ABANDONMENT.			
NOTICE O	OF INTENTION TO PULL OR	ALTER CASING	SUPPLEMENTAR	Y WELL HISTORY		_	
NOTICE (OF INTENTION TO ABANDON	WELL	Suppedner	it Report of Wel	1 Completion 2	K.	
	(INDIC.	ATE ABOVE BY CHECK MARK	NATURE OF REPORT,	NOTICE, OR OTHER DATA)		:::	
				October 2.	, 19_5	. 7	
	Carson Unit 32-14 is loca	ted 1980 ft. from	$\begin{bmatrix} N \\ 1 \end{bmatrix}$ line and $\begin{bmatrix} 1 \\ 1 \end{bmatrix}$	1980 ft. from (E)			
	14	2 5 0	12¥	NMPM			
	(Sec. and Sec. No.)	, <u>-</u> ,	(Range)	(Meridian)			
23	(Field)	San Ju	an r Subdivision)	(State or 1			
-2-57 -5-57 -19-57	Perforated four Practure treate Started pumping	1/2" boles/ft. d with 30,000 g	4880-4902', al cil, 1#/6	t 5067' with 200 4911-17', 4956 al 20-40 mesh au	ARI 1002_ELI		
70-21	initial Product	64/64" been. F. ien: Flowing, 40, 193 MCF ga	440 B/D gros	E/D rate. 9. 437 B/D clear Completed 9-24-	9 0 2 57.	ム	
I unders	tand that this plan of work	: must receive approval in 1	writing by the Geolog	cal Survey before operation	s may be commenced.		
Company	y Shell Gil	Company	•	····		erio ^{do} Se esta Se esta	
Address .	101 South	sehrend			The state of the s	3 46 00	
·····	Faraington	New Maxico	Ву	B. W. Shepard	ed.		
				Exploitation			