


(SUBMIT IN TRIPLICATE)

Land Office **Santa Fe, New Mex.**

Lease No. **SF078071**

Unit _____



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Spud and setting surface casing	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 4, 1956

Well No. **11-18** is located **660** ft. from **N** line and **1265** ft. from **E** line of sec. **18**
C Lot 2 NW 1/4, Sec. 18 **25N** **13W** **NMPM**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat **San Juan** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6404** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud on 6-28-56. Ran 9 joints 10 3/4 32.75 lb. new lap weld Spang surface casing, set at 197 with 100 sacks neat cement.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **F. R. Anderson, Petroleum Producer**

Address **901 Sherman St. Suite #108, Denver, Colorado**

By **Charles S. Peters**

Title **Geologist**