

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
E. W. Mudge No. 3
SF 078064
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <u>Salt Water Source</u>		7. UNIT AGREEMENT NAME <u>Carson Unit</u>	
2. NAME OF OPERATOR <u>Shell Oil Company</u>		8. FARM OR LEASE NAME <u>Native Source w</u>	
3. ADDRESS OF OPERATOR <u>1700 Broadway, Denver, Colorado 80290</u>		9. WELL NO. <u>6-23</u>	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) <u>At surface</u> <u>724' FNL & 2640' FEL Section 13</u>		10. FIELD AND POOL, OR WILDCAT <u>Bisti</u>	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>6380 KB</u>	
		12. COUNTY OR PARISH <u>San Juan</u>	13. STATE <u>N.M.</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

See attachment

WILL SEND FINAL SUNDRY WHEN LOCATION
CLEANED AND READY FOR INSPECTION

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Div. Opers. Engr. DATE 9/27/77

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

cc: NMO&GCC

*See Instructions on Reverse Side

PLUG AND ABANDON				BISTI
SHELL OIL COMPANY	LEASE	CARSON UNIT	WELL NO.	6-13 WSW
	DIVISION	WESTERN	ELEV	6380 KB
FROM: 9/22-27/77	COUNTY	SAN JUAN	STATE	NEW MEXICO

NEW MEXICO
BISTI FIELD

Carson Unit 6-13 WSW
(P&A)

"FR" TD 3805. PB 3789. AFE #570026 provides funds to plug & abandon well. 9/20 RU Bedford & pulled 1" & 7/8" rods.
SEP 22 1977

Carson Unit 6-13 WSW
(P&A)

TD 3805. PB 3789. No report.
SEP 23 1977

Carson Unit 6-13 WSW
(P&A)

TD 3805. PB 3789. No report.
SEP 26 1977

(Carson Unit 6-13 WSW
(P&A)

TD 3805. PB 3789. 9/21 Pulled 30 jts tbg; pull'g 30,000# over tbg wt. Tbg stuck 30 jts out of hole. 9/22 Ran 30 jts tbg back in hole. Cut tbg above seat'g nip & anchor; tbg still tight. 9/23 Spt'd 200 sx cmt plug thru stuck tbg over Allison Menefee perfs. 9/24 Perf'd tbg & csg @ 1200'. Spt'd 100 sx cmt; sqz'd 40 sx. Perf'd tbg & csg @ 400'. Spt'd 60 sx cmt; sqz'd 35 sx. Backed tbg off; got 10 jts. Pulled 10 jts & placed 10 sx cmt plug on sfc. Set abandonment marker & RD Bedford. SEP 27 1977
FINAL REPORT