


Santa Fe, New Mex.



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. _____
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 29, 1957

Carson Unit

Well No. 11-13 is located 660 ft. from [N] line and 660 ft. from [E] line of sec. 13

13

(1/4 Sec. and Sec. No.)

25N

(Twp.)

12E

(Range)

RMP

(Meridian)

Dist. ext.

(Field)

San Juan

(County or Subdivision)

New Mexico

(State or Territory)

The elevation ~~at the casing floor above sea level~~ is 6366 ft. (approx. ground)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

(Spudded 1-27-57)

1-28-57 ran (220') of 5 5/8", 28#, H-40 casing at 233' cemented with 150 sacks construction cement. Cement returns to surface. Finished 4:30 A.M.
1-29-57. Flanged up and waited on cement. Pressure tested casing and blowout equipment with 700 psi. for 15 minutes, OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company

Address 33 Richards Street

Salt Lake City, Utah

By

B. W. Shepard
B. W. Shepard

Title

Exploitation Engineer