

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-M338.4.
Approval expires 12-31-60.

Land Office Santa Fe, N. M.
Lease No. SF 078064
Unit Carson

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			
Notice of casing failure	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 11-13 is located 695 ft. from {N} line and 695 ft. from {E} line of sec. 13
July 17, 1964

13 (1/4 Sec. and Sec. No.) 25N (Twp.) 12W (Range) MTN (Meridian)
Sisti (Field) San Juan (County or Subdivision) New Mexico (State or Territory)



The elevation of the Kelly Lushing ~~derriek floor~~ above sea level is 6377 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Status: TD 5030. Csg. 8 5/8" @ 10.9', 4 1/2" @ 5030'. Perf. 4869-96, 4901-00, 4-02, 66-76

No remedial action contemplated since production rate will not justify repair work.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company

Address Box 120

Farmington, New Mexico

By

Bob Kazarian
Title Division Production Superintendent