

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe, New Mex.

Lease No. 57 07604

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

_____ April 16 _____, 19 58

Well No. 21-12 is located 660 ft. from N line and 1000 ft. from W line of sec. 13

34 13
($\frac{1}{4}$ Sec. and Sec. No.)

25E
(Twp.)

12N
(Range)

41N
(Meridian)

Hista
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)


The elevation of the ~~surface~~ of the surface is 6360 ft. (Approx. ground)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

(Spudded 4-15-58)

4-15, 16-58 Ran and cemented 8 5/8" 24#, J-55 casing at 103' with 100 sack treated cement. Good returns to surface. Flanged up and waited on cement. Tested BOP and casing with 700 psi 15 min., OK.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company

Address 101 E. Behrend
Farlington, New Mexico

Original signed by
P. S. MacALISTER, JR.

By D. W. Shepard
Title Exploitation Engineer