

	11		
X			

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Carson, N. M.
Lease No. 078067
Unit Carson

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 30, 1957

Carson

Well No. 14-11 is located 530 ft. from {N} line and 460 ft. from {E} line of sec. 11

11 (1/4 Sec. and Sec. No.) 25N (Twp.) 12E (Range) R1E (Meridian)

Dist 1 (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6212.82 ft. (approx. ground)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Proposed Work:

1. Drill 12-1/4" hole to 100'±.
2. Cement 8-5/8" casing at 100'± with 50 sacks construction cement.
3. Drill 7-7/8" hole to 4840'±.
4. Cement 4-1/2" casing at 4835'± with 150 sacks construction cement.
5. Clean out to 4820'±.
6. Perforate four 1/2" holes/ft. intervals determined b logs.
7. Sand-oil fracture with 30,000 gal. crude oil and 1-20/gal. sand.
8. Flow well into production, establish initial rate.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company

Address 101 E. Behrend

Farmington, N. M.

By J. H. G. [Signature]

Title Exploitation Engineer

NEW MEXICO OIL CONSERVATION COMMISSION

Well Location and Acreage Dedication Plat

Section A.

July 29, 1957

Operator **SHELL OIL COMPANY** Lease **CARSON UNIT** R. Mms SF 078067
 No. **14-11** Unit Letter **M** Section **11** Township **25 NORTH** Range **12 WEST**, NMPM
 Located **530** Feet From **the SOUTH** Line, **460** Feet From **the WEST** Line
 County **SAN JUAN** G. L. Elevation **6219.8** Dedicated Acreage **40** Acres
 Name of Producing Formation **Gallup** Pool **Bisti**

1. Is the Operator the only owner in the dedicated acreage outlined on the plat below?
 Yes ☒ No ☐
2. If the answer to question one is "no", have the interests of all the owners been consolidated by communitization agreement or otherwise? Yes ☐ No ☐ If answer is "yes", Type of Consolidation.
3. If the answer to question two is "no", list all the owners and their respective interests below.

Owner

Legal Description


Section B.

Note: All distances must be from corner boundaries of Section 11.

This is to certify that the information in Section A above is true and complete to the best of my knowledge and belief.

Shell Oil Company
 (Operator)
B. W. Shepard
 (Representative)
 101 S Behrend
 (Address)
 Farmington, New Mexico

TRM: Iron Pin 390' S 77° W of
 Location. Elev: 6230.61



This is to certify that the above plat was prepared from field notes of actual survey made by me or under my supervision and that the same are true and correct to the best of my knowledge and belief.

Date Surveyed **18 JULY 1957**

James P. Lese
 Registered Professional Engineer and/or Land Surveyor
JAMES P. LERSE **N. MEX. REG. No. 1463**



OIL CONSERVATION COMMISSION		
AZTEC DISTRICT OFFICE		
No. Copies Received		2
DISTRIBUTION		
	NO.	
Operator		
Santa Fe		
Promotion Office		
State Land Office		
U. S. G. S.		
Transporter		
Site	1	✓