

| | | | |
|---|----|--|--|
| | | | |
| | | | |
| | 11 | | |
| X | | | |

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe, N.M.
Lease No. SF 078067
Unit Carson

SUNDRY NOTICES AND REPORTS ON WELLS

| | |
|--|--|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY |
| NOTICE OF INTENTION TO ABANDON WELL | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. Carson 14-11 is located 530 ft. from N line and 460 ft. from NE line of sec. 11
SW 11 25N 12W T14N
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Dist 4 San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6200 ft. (approx. ground)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

(Spudded 9-4-57)

9-3,4-57 Ran and cemented 8-5/8" 24#, J-55 casing at 116' with 85 sacks treated cement. Good returns to surface. Flarged up and waited on cement. Test BOP and casing with 700 psi. for 15 min. O.K.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations are commenced.

Company Shell Oil Company
Address 101 South Behrend Avenue
Farmington, New Mexico

By B. W. Shepard
B. W. Shepard
Title Exploitation Engineer