Land Office	Santa	Pe,	M.M.	•
Lease No	S P 07 8	3066		3,50
Unit	70-10-0 -1	•		

SUNDRY NOTICES AND REPORTS ON WELLS

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)					
NOTICE OF INTENTION TO ABANDON WELL					
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY			
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	<u></u>	SUBSEQUENT REPORT OF ABANDONMENT			
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.			
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING			
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING			

Well No. 11-10 is located 660 ft. from S line and 660 ft. from W line of sec. 10

The elevation of the derrick floor above see level is 6237 ft. (approx. ground)

DETAILS OF WORK


County or Subdivision)

(State or Territory)

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

(Speeded 5-20-56)

8-21-56 Ran and commented 8-5/8", 32%, J-55 casing at 227 with 100 sacks treated construction cament. Good returns to surface. Finished 12-55 P.M. 8-21-56. Waited on coment and flanged up. Tested blowout equipment and casing with 700 psi for 15 min., OK.



No.