

(SUBMIT IN TRIPLICATE)

Land Office Santa Fe  
Lease No. NM 04224  
Unit Quitau

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 7th, 1956

Well No. 9 is located 1171 ft. from N line and 1242 ft. from W line of sec. 11

SW/4 SW/4 Sec. 11  
(1/4 Sec. and Sec. No.)

25N  
(Twp.)

8W  
(Range)

N.M.P.M.  
(Meridian)

Ballard PC  
(Field)

San Juan  
(County or Subdivision)

New Mexico  
(State or Territory)


The elevation of the derrick floor above sea level is 6991 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

10- 3-55 TD 103' RKB. Set 3 joints 95' of 8-5/8" OD 24# J-55 casing at 103' with 80 sacks cement, circulated.

10- 8-55 Pressured up on casing to 500#. No pressure decrease in 30 minutes.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company BENSON-MONTIN

Address 405 1/2 West Broadway

Farmington, New Mexico

By Alfred H. Green

Title Field Superintendent