orm 9-331 May 1963)		UNITED STATES	TEDIAD	SUBMIT IN TRIPLICATION OF		Form approved, Budget Bureau No.		
		MENT OF THE IN		verse side)	-	5. LEASE DESIGNATION AND 8	EKIAL NO.	
		SEOLOGICAL SURV	EY		.	SF 078063		
(Do	SUNDRY NOT not use this form for proportion Use "APPLICATION OF THE PROPERTY O	ICES AND REPORTION FOR PERMIT—" for	RTS ON r plug back to such propose	WELLS		6. IF INDIAN, ALLOTTEE OR TH	RIBE NAME	
			DE	CEIV		7. UNIT AGREEMENT NAME		
OIL X GAS WELL OTHER			LAN	AN 24 1983		Carson Unit		
NAME OF	F OPERATOR	.t. Componi		ANZA	Ì	8. FARM OR LEASE NAME		
	Hixon Developmer	it Company		SURVEY		9. WELL NO.		
. ADDRESS	D O BOY 2810 F	Carminaton New N	Maxico -	R ZEOLOGICAL N. M.		n **		
Hixon Development Company ADDRESS OF OPERATOR P.O. Box 2810, Farmington, New Mexico & CATON OF WELL (Report location clearly and in accordance with any State Fedure ments.*						10. FIELD AND POOL, OR WILDCAT		
See also space 17 below.) At surface						_		
At suitace					-	Bisti Lower Gallup 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
	10121 ECT 5201	EUI Continu 7	т25M D	1 1 1.7	1	BORYET ON ABBA		
1813' FSL, 530' FWL, Section 7, T25N, R11W						Section 7, T25N,	R11W	
4. PERMIT	No.	15. ELEVATIONS (Show wh	ether DF, RT, G	R, etc.)		12. COUNTY OR PARISH 13.	STATE	
		6317' KB				San Juan N	М	
6.	Charle A	opropriate Box To Indi	cate Natur	e of Notice Report o	r O	ther Data		
-	NOTICE OF INTER	•		•		INT REPORT OF:		
			¬			REPAIRING WELL		
		PULL OR ALTER CASING	-	WATER SHUT-OFF		ALTERING CASING		
		MULTIPLE COMPLETE	-	FRACTURE TREATMENT		ABANDONMENT*		
вноот		ABANDON*	-	(Other) Return	السيا ۲ م		${\mathbf{x}}$	
REPAIR WELL CHANGE PLANS (Other)				(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)				
	•					ncluding estimated date of st	arting any	
nent	osed work. If well is directi to this work.) *	onally drilled, give subsurfs	ace locations		rticai	depths for hit markers and z	ones perti-	
nent	used work. If well is direction to this work.)* The subject well	CRATIONS (Clearly state all ponally drilled, give subsurfs was returned to flush joint line.	o produc	tion 1/21/83.	4015	5.83' of	ones perti-	
nent	The subject well 4-1/2" 10.5# FS4	onally drilled, give subsurts	produc	tion 1/21/83. 4	4015	5.83' of ith 250	ones perti-	
nent	The subject well 4-1/2" 10.5# FS4 sacks of cement.	was returned to	o productions of production production was sole to 4	tion 1/21/83. 4 run and cemented	4015 d wi	5.83' of ith 250 was	ones perti-	

18. I hereby certify that the foregoing is true and correct 1/21/83 Petroleum Engineer DATE (This space for Federal or State office use) DATE APPROVED BY PETER FOR ALL IN ANTIONED TITLE

JAN 2 3 1983

*See Instructions on Reverse Side

